

**POWDER SIEVING SYSTEM – BATCH (HOPPER MOUNTING STYLE)**  
**SCOPE OF SUPPLY**

- a) Siever Batch with pneumatic vibrator (Hopper Mounting style) 1 No.

**PNEUMATIC DATA**

Maximum input pressure	5 bar
Optimum input pressure	3 bar
Maximum water vapour content in compressed air	1.3 g/Nm <sup>3</sup>
Maximum oil vapour content in compressed air	0.1 ppm
Maximum Compressed air consumption	13.2m <sup>3</sup> / hr – Approx 8 cfm