

# EFFICIENCY

Worldwide  
New

# METER



Measure charge in Tribo Cloud

Measure charge in Corona Cloud

## INSTANTLY MEASURE QUALITY OF GUN AS WELL AS POWDER

- Measure Corona tip voltage (0-100 KV DC) - check gun quality.
- Measure level of charge in a powder cloud (0-100%) - compare powder quality.
- Display +ve or -ve polarity.
- Measure ground quality.

Use for all brands of both Manual & Auto Guns.

